



SUPPLY VOLTAGE

VAC	VDC	
Phase (L)	+ VDC	1
Neutral (N)	- VDC	2
Earth (PE)	Earth (PE)	3

(See 4.1 Technical features)

OUTPUT SIGNALS

RELAY ALLARM MAXIMUM dP (K1)

RELAY ALLARM MINIMUM dP (K2)

OUTPUT SIGNAL 4 + 20 mA
ACTIVE SIGNAL POWERED

LEGEND	
F1	5x20 Line protection fuse
J1	Connection clamps
JP1	Supply voltage selection jumper
RL41	Output relay K1
RL42	Output relay K2
T1	Input transformer
TS61	Differential pressure transducer
+P1	dP pressure side dirty
+P2	dP pressure side clean

